

All was going well with our new pool and cabana as shown in this photo taken on April 5, 2008. However, our pool contractor just walked out, with about \$240,000 in his pocket and with only promises to continue work on our pool. Here is his web page: <http://www.boomerblockpools.com/designer.htm>.



The rest of the pages are pictures of the pool as they are today, two months later. This is how the back yard looks from the front street and our driveway.



This hill of dirt is about 5 feet tall.



This is what we see behind our house. Note there was no cleanup effort made.



Boomer specifically asked for the money to buy the pool equipment and this is what we now have –nothing but a mess and a \$300,000 loan.



Boomer would not pay for the decking with money we gave him – thousands.



Trash is everywhere.



The water is very alkaline, and as I found out, will kill your skin.





This is how it looks behind our house where the sewer line runs.



The sewer line runs past this set of steps.



And the sewer and water lines run up to the cabana here.




Looking toward the pool from the same spot....




Here is looking from the other end of the lower recirculation pool.



This is looking down the side of our house where the sewer and water lines run. We had to pay an extra \$800 just to get the sewer line covered up. Boomer was supposed to provide all this, but you can see that he didn't finish.



This is just past where the sewer line comes into the cabana. Boomer was supposed to put a limestone deck walkway here. We paid him extra for this.



This is looking back in the opposite direction at the same location.



The decking in the cabana was never put in by Boomer. The ice maker installer said this was the worst flooring job he had ever seen.



Walking through the cabana and looking out the opening on the other side we see:



And we see this....



Here is outside the cabana looking back in the opening we were just standing in.



Here is gravel Boomer's crews left behind.



Spoils left over from diggings.



This is the back side of the 5 ft high dirt mound looking back toward the street.



And from the dirt mound, this is what it looks like looking at our house.



Here is a closeup view from the walkway leading to the decking behind the house.



The alkaline water is also in the bottom of the main pool.



Here is the swim lane. It's dry.



More trash.



We used to have drainage here. Now its blocked by a mound of dirt.



Cheryl and I had to finish the gas line connection at the front of the house ourselves. We finally contacted the inspector and paid him to do a new inspection. Boomer was supposed to do this work; however, he ignored us.

